


3450 16th Ave. W., Seattle, WA 98119 • 206-634-1656 • Toll Free 866-634-1656 • Fax 206-691-3712 • www.dustystrings.com

D500 Stringing Diagram for instruments after serial #13168



All strings are loop end. Wire gauges are shown in inches. PB indicates phosphor bronze wire. PBW indicates phosphor bronze wound. SSW indicates stainless steel wound. Unspecified strings are plain steel. Dots indicate marked courses. Superscript numbers indicate octave. C4 is middle C.